

## **Crude Stabilizer - NGL**

Texas, USA

## **Problem**

NGL product has high levels of black powder contamination coming out of the stabilizer column. The contamination was causing damage to the pumps, meters, and valves downstream; off-spec product was getting rejected by third party pipelines.

## **Solution**

A magnetic separator system was installed in the discharge of the NGL going to the pipeline pumps.

## Results

Analysis of the contamination determined a composition of 83% iron oxide, 9% carbon, 7% dust, as well as dirt, fibers, a grass seed, and trace amounts of chrome, manganese and titanium.

Application Data	
Operating Fluid	NGL
Operating Pressure	200 psi
Operating Temperature	90° F
Max. Flow Rate	200 gpm





